


Fig. 4a Bicycle Crash Modes - Santa Barbara, CA, 1974

Ranking goes clockwise around pie chart, starting with "Defective Road Surface at #1



Source: John Forester *Bicycle Transportation* 2nd edn. MIT Press, Table 5-3 p 43. Based on Santa Barbara Cyclists study, 1974, by Kenneth Cross for National Safety Council